

US Army Corps of Engineers Buffalo District 1776 Niagara Street Buffalo, New York 14207-3199

## Notice to Navigation Interests

L08 – 32	JULY 30, 2008
Notice No.	Date
Waterway	

Lake Erie, Ohio

LRB-TD-ONS



Condition of Federal Navigation Channel Huron Harbor, Huron, Ohio

- 1. Condition surveys performed within the Federal navigation Channel at Huron Harbor, Ohio during the month of May 2008 indicate shoaling has reduced depths to those shown on the attached standard tabular form and channel condition drawings.
- 2. Soundings are in feet and referred to Low Water Datum (LWD) 569.2 feet above Mean Water Level (MWL) at Rimouski, Quebec (International Great Lakes Datum 1985).
- 3. Vessel operators are advised to use caution when navigating in this area.
- 4. Copies of the sounding print for Huron Ohio consisting of (3) sheets, 08S-HUR-1/1 thru 1/3, at a cost of \$2.50 per sheet will be furnished upon receipt of a check in the full amount made payable to: United States Army Engineer District, Buffalo. Requests should be addressed to: District Commander, U.S. Army Engineer District, Buffalo, ATTN: NY/PA O&M Office, 1776 Niagara Street, Buffalo, New York 14207, requesting exact number or copies of sheets by file number. A point of contact and phone number must be indicated to facilitate response to the request. To download the same information and other related materials at no cost, simply point your web browsers to <a href="http://www.lrb.usace.army.mil/WhoWeAre/WaterMgmt/survey/survey.html">http://www.lrb.usace.army.mil/WhoWeAre/WaterMgmt/survey/survey.html</a> click on the year and then locate the harbor on the table of harbors.
- 5. Buffalo district's point of contact in reference to the exact number of sheets, file number, and the availability of any later information pertaining to the area is Mr. Kelly L. Maccarone, Chief of the Survey Section, Buffalo District, and may be contacted by phone at 716-879-4285.

RAYMOND N. LEWIS Chief, NY/PA Operations and Maintenance Office

## REPORT OF CHANNEL CONDITIONS (FOR CHANNELS LESS THAN 400 FEET WIDE) (ER-1330-2-316)

PAGE 2 OF 4 PAGES

DATE JULY 30, 2008

TO: ACCOMPANY LOCAL NOTICE TO NAVIGATION INTERESTS, DATED

FROM: U.S. ARMY CORPS OF ENGINEERS, BUFFALO DISTRICT 1776 NIAGARA STREET, BUFFALO, NY 14207-3199 (716) 879-4292 FAX (716) 879-4356

RIVER/HARBOR NAME AND STATE MINIMUM DEPTHS IN CHANNEL ENTERING HURON HARBOR, HURON, OHIO FROM SEAWARD AUTHORIZED PROJECT LEFT **RIGHT** DATE OUTSIDE MIDDLE HALF OUTSIDE NAME OF CHANNEL OF WIDTH LENGTH **DEPTH QUARTER** (feet) **QUARTER SURVEY** (feet) (feet) (feet) (feet) (feet) (A) LAKE APPROACH MAY 400 22.5 8400 (a) 29 21.6 22.5 CHANNEL. 2008 (B) ENTRANCE CHANNEL. FROM LAKE APPROACH MAY CHANNEL TO THE NORTH 400-300 700 29 13.3 16.0 17.3 2008 END OF THE EAST BREAKWATER. (C) ENTRACNE CHANNEL, FROM THE NORTH END OF MAY 1900 300-150 28 13.9 15.7 7.5 THE EAST BREAKWATER 2008 TO SLIP #1. (D) HURON RIVER MAY 120-350 1500 27 20.4 20.3 21.0 CHANNEL. 2008 MAY (E) TURNING BASIN 10.9 0-400 600 (b) 21 11.6 11.3 2008

REMARKS: (a) LENGTH VARIES DEPENDING ON THE LOCATION OF THE 29 FOOT CONTOUR IN LAKE ERIE.

(b) IRREGULARLY SHAPED, SEE PROJECT CONDITION DRAWINGS.

L 08

2008

30.

DATED JULY

NAV I GAT I ON

2

NOT ICE

LOCAL

**ACCOMPANY** 

2

L 08

2008

30,

DATED

NAV I GAT I ON

2

NOT ICE

LOCAL

**ACCOMPANY** 

2